

AP Firmware 3.6.0 Release Notes

Release Date: May 31st 2018

Contents

- 1. Devices Supported
- 2. Important Notices
- 3. Obtaining the Firmware
- 4. Feature Improvements
- 5. Issues Resolved
- 6. Report a Bug

1. Devices Supported

This firmware release supports the following devices:

Pepwave AP: AP One AC mini / AP One Enterprise / AP One Flex / AP One Rugged

2. Important Notices

WDS Does not Function on this Firmware: WDS is not working on this firmware. If your deployment uses WDS, please do not upgrade to this firmware

3. Obtaining the Firmware

AP Firmware 3.6.0 can be obtained here: https://www.peplink.com/support/downloads/

4. Feature Improvements

Reference	Feature
16044	[802.11r] Added support for 802.11r, which improves the transition process of a mobile client as it moves between access points.
15505	[RADIUS Authentication] Both Device Name and MAC address can now be used for the NAS-Identifier on RADIUS authentication.



15712	[Client List] The client list now shows the host names of the clients as well the MAC address.
15900	[Configurable Timeout] The timeout period for each web session can now be configured from the Web UI.
16462	[Transmit Power] Added ability to select a specific dBm to offset the existing transmit power setting by.
16642	[Connection Stability] Improved connectivity stability for Apple devices.

5. Issue Resolved

Reference	Feature
17237	[IC2 Remote Web Admin] InControl is unable to reboot a device using the device tools.

6. Known Issue

Reference	Issue
18108	[Client List Display] In the "Connected Clients" list under Status > Client list, the TX rate is not correct.

7. Report a Bug

To report a bug, please open a support ticket at https://contact.peplink.com/secure/create-support-ticket.html.

For the latest development news, and known issues, take a look at our forums: https://forum.peplink.com/