

SIM Injector Firmware 1.2.4

Release Notes

Release Date: Apr 22, 2025

Resolved Issues

Reference	Description
33816	Fixed an issue where a SIM injector would stop accepting new SIM link requests after repeated attempts from multiple cellular connections
33314	Fixed an issue where InControl displayed incorrect system uptime
33833	Fixed an issue where some SIM cards were not detected during initialization

Report an Issue

To report an issue, please open a support ticket at:

<https://ticket.peplink.com/>

For the latest development news and known issues, take a look at our forums:

<https://forum.peplink.com/>