

# MAX Adapter Firmware 1.1.2 Release Notes

Release Date: Nov 13, 2024

[Changes since version 1.0.6](#)

## Improvements

Description
Added support for separate profile settings for different SIM cards
Added support for Active Session in Web UI
Added support for SMS Commands
Added support to update the SIM card number
Added support for DHCP Server Logging
Added support for SIM toolkit with SMS functionality
Added support for SIM PIN
Added support for SIM Priority
Added support for Health Check Settings
Added support for Bandwidth Allowance Monitor
Added support for WAN Connection Settings
Added support for IP Passthrough

## Resolved Issues

Description
Fixed an issue where the WebUI displayed the default APN as “internet” when a SIM card was removed or during SIM switching
Fixed an issue with page navigation when changing the default password
Fixed issue of default APN being set to “internet” when carrier info was unavailable
Fixed issue with incorrect status updates for “Reboot” and “Restore Factory Settings” on InControl
Fixed issue of repeated SMS command actions
Fixed issue of incorrect TTL value used for network traffic

## Report an Issue

To report an issue, please open a support ticket at:

<https://ticket.peplink.com/>

For the latest development news and known issues, take a look at our forums:

<https://forum.peplink.com/>