

# SIM Injector Firmware 1.1.137

## Release Notes

Release Date: Aug 29, 2024

### Improvements

Description
Added an extra health check to the FusionSIM Controller
Fixed the issue preventing reconnection to the FusionSIM Controller
Fixed the SIM Injector connection issue during startup of the FusionSIM Controller
Fixed the issue of SIM Injector not re-acquiring IP after LAN reconnection
Fixed the issue to ensure proper reading of the SIM card

### Report an Issue

To report an issue, please open a support ticket at:

<https://ticket.peplink.com/>

For the latest development news and known issues, take a look at our forums:

<https://forum.peplink.com/>