

SIM Injector Firmware 1.1.140

Release Notes

Release Date: Nov 21, 2024

Improvements

Description
Improved the connection setup time for RemoteSIM/FusionSIM

Resolved Issues

Description
Fixed a connection issue for some SIM cards and incorrect "SIM PIN Required" or "Incorrect PIN" status
Fixed a potential SIM Injector discovery issue
Fixed an issue that might cause system performance degradation

Report an Issue

To report an issue, please open a support ticket at:

<https://ticket.peplink.com/>

For the latest development news and known issues, take a look at our forums:

<https://forum.peplink.com/>