

# AP One Firmware 3.9.4 RC 2 Release Notes

Release Date: Jul 16, 2024

### **Devices Supported**

This firmware release supports the following devices:

- AP One AX
- AP One AX Lite
- AP Pro AX
- AP One Mini HW3
- AP One Rugged HW2
- AP One AC Mini HW2
- AP One Flex HW4



#### **New Features**

| Reference | Description  |
|-----------|--|
| 31822     | [Beta 1] Added Private Pre-Shared Key (PPSK) security support in SSID with Security Policy "WPA/WPA2 Personal" and "WAP2 Personal" (Except AP One AC Mini HW2 and AP One Flex HW4) |

## **Improvements**

| Reference | Description   |
|-----------|---|
| 29844     | [RC 2] Added an option to use the PoE port as the WAN port in router mode for AP One Rugged HW2 |
| 31979     | [Beta 1] Added "Mesh Link Information" in AP > Status > Mesh / WDS                              |
| 31411     | [Beta 1] Added custom name support for GPIO in event logs on AP One Rugged                      |
| 31868     | [Beta 1] Added EtherType support on SSID firewall   |
| 32016     | [Beta 1] Added Security Policy and Fast Transition (FT) information to the AP Event Log         |
| 30266     | [Beta 1] Added support for RADIUS Dynamic Authorization Extensions (RFC 5176) in WLAN networks  |
| 25474     | [Beta 1] Added support for the ethernet port to act as LAN port in router mode                  |
| 31338     | [Beta 1] Added Ukraine to Wi-Fi operating country selection                                     |
| 31780     | [Beta 1] Mesh AP can now connect to Root AP when WAN is down                                    |



#### **Resolved Issues**

| Reference | Description  |
|-----------|--|
| 32535     | [RC 1] Fixed the issue of client count not displayed correctly on InControl  |
| 32506     | [RC 1] Fixed the issue where PoE port as uplink, traffic was not displayed on the InControl dashboard  |
| 32103     | [Beta 1] Fixed an issue of stability on AP One Rugged related to Wi-Fi client connectivity (Fixed in: 3.9.3s014)   |
| 31832     | [Beta 1] Fixed issue with auto channel update on Wi-Fi APs triggered by InControl or AP Controller   |
| 32038     | [Beta 1] Fixed issue with laptops unable to connect to SSID using OWE security (Fixed in: 3.9.3s013)   |
| 31905     | [Beta 1] Fixed the issue where some legacy Wi-Fi clients required Wi-Fi 6 to be disabled to connect, but were still unable to connect even after disabling Wi-Fi 6 |
| 30986     | [Beta 1] Improved stability in chained mesh networks with mixed Ethernet and Wi-Fi links (Fixed in: 3.9.3s009)   |

To report an issue, please open a support ticket at:

https://ticket.peplink.com/

For the latest development news and known issues, take a look at our forums: <a href="https://forum.peplink.com/">https://forum.peplink.com/</a>