

# AP One Firmware 3.9.7 Release Notes

Release Date: Mar 23, 2026

## Devices Supported

This firmware release supports the following devices:

- AP One Enterprise HW3

## Improvements

Reference	Description
35965	[RC 1] [Captive Portal] Updated Captive Portal SSL certificate
35468	[RC 1] Changed the default SSID security mode to WPA2/WPA3 Personal.

## Resolved Issues

Reference	Description
35935	[RC 1] [Security Advisory] Fixed a vulnerability in the API that could allow remote code execution
36122	[RC 2] Fixed a VLAN configuration issue in bridge mode that could cause management VLAN changes to fail to apply.
36176	[RC 2] Fixed an issue where wireless clients could intermittently fail to obtain an IP address in some VLAN bridge deployments.
35859	[RC 1] Added Web Admin support for disabling Message-Authenticator enforcement for MAC Authentication with RADIUS.
35838	[RC 1] Fixed 320 MHz initialization timeouts on EU channels 65-93.
35293	[RC 1] Fixed a stability issue that could cause a crash when the SSID count reached the system limit.
35489	[RC 1] Fixed an error that could appear when switching to countries that do not support 6 GHz by default.
35490	[RC 1] Fixed an issue where 6 GHz mesh could unexpectedly fall back to 5 GHz.
35498	[RC 1] Fixed an issue where 6 GHz settings pushed from InControl could display incorrectly in Web Admin.

<b>35292</b>	<b>[RC 1]</b> Fixed an issue where a mesh AP could fail to obtain an IP address via DHCP.
<b>35911</b>	<b>[RC 1]</b> Fixed an issue where newly added non-WPA3 SSIDs could incorrectly include 6 GHz.
<b>35491</b>	<b>[RC 1]</b> Fixed failures when manually configuring 6 GHz EHT40 channels.
<b>35562</b>	<b>[RC 1]</b> Fixed incorrect real-time client counts on the Access Point status page.
<b>35673</b>	<b>[RC 1]</b> Fixed incorrect SSID status reporting to AP Controller.

## Report an Issue

To report an issue, please open a support ticket at:

<https://ticket.peplink.com/>

For the latest development news and known issues, take a look at our forums:

<https://forum.peplink.com/>